

FIG. 1




FIG. 2

PRINTER 100




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7A

FIG. 7

FIG. 7A
FIG. 7B




FIG. 7B




FIG. 8




FIG. 9B




FIG. 9C




FIG. 10A

FIG. 10

FIG. 10A

FIG. 10B




FIG. 10B




FIG. 11

INITIAL DATA
SETTING




FIG. 12

DATA SETTING
n=7




FIG. 13




FIG. 14




FIG. 15A




FIG. 15B

COORDINATE DATA : COEFFICIENT DATA	
$P_0 (x_0, y_0)$	a_0
$P_1 (x_1, y_1)$	a_1
$P_2 (x_2, y_2)$	a_2
$P_3 (x_3, y_3)$	a_3
$P_4 (x_4, y_4)$	a_4
$P_5 (x_5, y_5)$	a_5
$P_6 (x_6, y_6)$	a_6
$P_7 (x_7, y_7)$	a_7
$P_8 (x_8, y_8)$	

FIG. 15C

$$\text{OUTPUT DENSITY} = \text{int} \{a_4 * (\text{INPUT DENSITY} - x_4) + y_4\}$$

FIG. 15D

L3	L2	L1	CC	U1	U2	U3
-3	-2	2	4	2	-2	-3

FIG. 16A

FIG. 16

FIG. 16A

FIG. 16B




FIG. 16B

